



Vehicle Inspection Report

Inspection Completed By: Bryan Boyd, Master Technician, Ken Caryl Imports

Year/Make/Model: 2017 Aston Martin DB11
VIN: SCFRMFAV7HGL03046
Stock #: 2336

TIRES	>6/32	4-6/32	<4/32	Notes
LF				7/32
RF				7/32
LR				7/32
RR				7/32

TEST DRIVE	Passing	Future Attention	Immediate Attention	Notes
Maintenance Reminders				
Malfunction Lights On				
Acceleration/Performance				
Transmission/Clutch Performance				
Braking Performance/Noise				
Steering Wheel Centered/Pulling				
Horn Operation				
Windshield Condition				
Windshield Wiper/Jet Operation				
Door Window Operation				
Sunroof				
Media and Infotainment				
Mirrors and Seats				
Climate Control Operation				
Dome Light Operation				
Additional Interior Notes				
Abnormal Noises/Feelings				
Parking Brake Operation				
Front Exterior Lights				
Wheels				
Rear Exterior Lights				
Paint Condition				

FLUIDS	Passing	Future Attention	Immediate Attention	Notes
Engine Oil				
Coolant				
Power Steering Fluid				
Transmission Fluid				
Brake Fluid Condition				

MECHANICAL	Passing	Future Attention	Immediate Attention	Notes
Front Suspensiton/Steering				
Front Brakes				6mm
Drive Belt Condition				
Front Axles				
Spare Tire and Equipment				
Rear Suspension				
Rear Brakes				7mm
Rear Axles				
Engine Oil Leaks				
Cooling System Leaks				
Power Steering Fluid Leaks				
Driveshaft Condition				
Drivetrain Fluids				Fluids clean and at correct level
Drivetrain Mounts				
Exhaust Condition				
Engine Air Filter Service Interval				
Cabin Air Filter Service Interval				
Spark Plug Service Interval				

OTHER TECH NOTES

Inspected 5.2L twin-turbo V12 for oil or coolant seepage around the turbocharger assemblies and engine valley – no issues noted.
Verified adaptive damping system and electronic suspension operate properly through all drive modes with no warning messages or abnormal operation.
Checked bonded aluminum body structure and exterior panel fitment for evidence of previous repairs or irregular panel alignment – no concerns noted.
Inspected front suspension and steering components for excessive wear or abnormal play – no abnormalities observed.