



Vehicle Inspection Report

Inspection Completed By: Bryan Boyd, Master Technician, Ken Caryl Imports

Year/Make/Model: 2018 Land Rover Range Rover Autobiography

VIN: SALGV2RE3JA508364

Stock #: 2311

TIRES	>6/32	4-6/32	<4/32	Notes
LF				7/32
RF				7/32
LR				7/32
RR				7/32

TEST DRIVE	Passing	Future Attention	Immediate Attention	Notes
Maintenance Reminders				
Malfunction Lights On				
Acceleration/Performance				
Transmission/Clutch Performance				
Braking Performance/Noise				
Steering Wheel Centered/Pulling				
Horn Operation				
Windshield Condition				
Windshield Wiper/Jet Operation				
Door Window Operation				
Sunroof				
Media and Infotainment				
Mirrors and Seats				
Climate Control Operation				
Dome Light Operation				
Additional Interior Notes				Hinge broken on rear armrest console - still operational
Abnormal Noises/Feelings				
Parking Brake Operation				
Front Exterior Lights				Driver's side headllight replaced
Wheels				
Rear Exterior Lights				
Paint Condition				Very small door ding front driver's door

FLUIDS	Passing	Future Attention	Immediate Attention	Notes
Engine Oil				Oil Service Completed.
Coolant				
Power Steering Fluid				
Transmission Fluid				
Brake Fluid Condition				

MECHANICAL	Passing	Future Attention	Immediate Attention	Notes
Front Suspensiton/Steering				Passenger front strut replaced, front air suspension valve block replaced 8mm
Front Brakes				
Drive Belt Condition				
Front Axles				
Spare Tire and Equipment				
Rear Suspension				8mm
Rear Brakes				
Rear Axles				
Engine Oil Leaks				
Cooling System Leaks				
Power Steering Fluid Leaks				Coolant crossover assembly replaced
Driveshaft Condition				Fluids clean and at correct level
Drivetrain Fluids				
Drivetrain Mounts				
Exhaust Condition				
Engine Air Filter Service Interval				
Cabin Air Filter Service Interval				
Spark Plug Service Interval				

OTHER TECH NOTES

Supercharged V8 runs smoothly with strong power delivery and no abnormal engine noise or drivability concerns noted.
Air suspension system operates properly through its height settings, with no significant suspension noise or warning messages observed during inspection.
Cooling system and common leak-prone areas were inspected with no significant active fluid leaks noted after crossover assembly replacement
Brakes, steering, drivetrain, and major electrical functions were checked and appear to be operating normally.