



Vehicle Inspection Report

Inspection Completed By: Bryan Boyd, Master Technician, Ken Caryl Imports

Year/Make/Model: 2021 Porsche 911 Turbo S
VIN: WP0AD2A93MS258850
Stock #: 2337

TIRES	>6/32	4-6/32	<4/32	Notes
LF				9/32
RF				9/32
LR				7/32
RR				7/32

TEST DRIVE	Passing	Future Attention	Immediate Attention	Notes
Maintenance Reminders				
Malfunction Lights On				
Acceleration/Performance				
Transmission/Clutch Performance				
Braking Performance/Noise				
Steering Wheel Centered/Pulling				
Horn Operation				
Windshield Condition				
Windshield Wiper/Jet Operation				
Door Window Operation				
Sunroof				
Media and Infotainment				
Mirrors and Seats				
Climate Control Operation				
Dome Light Operation				
Additional Interior Notes				
Abnormal Noises/Feelings				
Parking Brake Operation				
Front Exterior Lights				
Wheels				
Rear Exterior Lights				
Paint Condition				

FLUIDS	Passing	Future Attention	Immediate Attention	Notes
Engine Oil				Oil Service Completed
Coolant				
Power Steering Fluid				
Transmission Fluid				
Brake Fluid Condition				

MECHANICAL	Passing	Future Attention	Immediate Attention	Notes
Front Suspensiton/Steering				10mm
Front Brakes				
Drive Belt Condition				
Front Axles				
Spare Tire and Equipment				
Rear Suspension				10mm
Rear Brakes				
Rear Axles				
Engine Oil Leaks				
Cooling System Leaks				
Power Steering Fluid Leaks				Fluids clean and at correct level
Driveshaft Condition				
Drivetrain Fluids				
Drivetrain Mounts				
Exhaust Condition				
Engine Air Filter Service Interval				
Cabin Air Filter Service Interval				
Spark Plug Service Interval				

OTHER TECH NOTES

Inspected 3.8L twin-turbo flat-six for oil or coolant seepage around turbocharger plumbing and engine sealing surfaces – no issues noted.
Checked front cooling system components and radiator inlets for damage or excessive debris accumulation, a common inspection point on 992 models – no concerns noted.
Verified proper operation of active rear spoiler and adaptive aerodynamic systems through all drive modes.
Inspected PCCB brake components (if equipped) for rotor condition and abnormal wear – operating as expected.