



Vehicle Inspection Report

Inspection Completed By: Bryan Boyd, Master Technician, Ken Caryl Imports

Year/Make/Model: 2021 Mercedes-Benz G63
VIN: W1NYC7HJ8MX391081
Stock #: 2333

TIRES	>6/32	4-6/32	<4/32	Notes
LF				12/32
RF				12/32
LR				12/32
RR				12/32

TEST DRIVE	Passing	Future Attention	Immediate Attention	Notes
Maintenance Reminders				
Malfunction Lights On				
Acceleration/Performance				
Transmission/Clutch Performance				
Braking Performance/Noise				
Steering Wheel Centered/Pulling				
Horn Operation				
Windshield Condition				
Windshield Wiper/Jet Operation				
Door Window Operation				
Sunroof				
Media and Infotainment				
Mirrors and Seats				
Climate Control Operation				
Dome Light Operation				
Additional Interior Notes				
Abnormal Noises/Feelings				
Parking Brake Operation				
Front Exterior Lights				
Wheels				Aftermarket
Rear Exterior Lights				
Paint Condition				Vinyl Wrapped - great condition

FLUIDS	Passing	Future Attention	Immediate Attention	Notes
Engine Oil				Oil Service Completed
Coolant				
Power Steering Fluid				
Transmission Fluid				
Brake Fluid Condition				

MECHANICAL	Passing	Future Attention	Immediate Attention	Notes
Front Suspensiton/Steering				Aftermarket lift/level kit installed 7mm
Front Brakes				
Drive Belt Condition				
Front Axles				
Spare Tire and Equipment				
Rear Suspension				Aftermarket lift/level kit installed 8mm
Rear Brakes				
Rear Axles				
Engine Oil Leaks				
Cooling System Leaks				
Power Steering Fluid Leaks				
Driveshaft Condition				
Drivetrain Fluids				Fluids clean and at correct level
Drivetrain Mounts				
Exhaust Condition				
Engine Air Filter Service Interval				
Cabin Air Filter Service Interval				
Spark Plug Service Interval				

OTHER TECH NOTES

Inspected 4.0L biturbo V8 for oil or coolant leaks around the turbocharger and engine valley areas – no issues noted.
Verified AMG Ride Control suspension and adaptive damping system operate properly with no abnormal noises or warning messages present.
Checked front axle, steering, and suspension components for looseness or wear, a common inspection point on G-Class models – no abnormalities observed.
Checked MBUX infotainment system and 360° camera system for proper operation with no faults present.