Vehicle Inspection Report

Inspection Completed By: Bryan Boyd, Master Technician, Ken Caryl Imports

Year/Make/Model: 2011 BMW 1 Series 128i
VIN: WBAUL7C56BVM79889
Stock #: 2340

TIRES	>6/32	4-6/32	<4/32	Notes
LF	✔			7/32
RF	✔			7/32
LR	✔			7/32
RR	✔			7/32

TEST DRIVE	Passing	Future Attention	Immediate Attention	Notes
Maintenance Reminders	✔			
Malfunction Lights On	✔			
Acceleration/Performance	✔			
Transmission/Clutch Performance	✔			
Braking Performance/Noise	✔			
Steering Wheel Centered/Pulling	✔			
Horn Operation	✔			
Windshield Condition	✔			
Windshield Wiper/Jet Operation	✔			
Door Window Operation	✔			
Sunroof	✔			
Media and Infotainment	✔			
Mirrors and Seats	✔			
Climate Control Operation	✔			
Dome Light Operation	✔			
Additional Interior Notes	✔			Drivers door lock knob missing
Abnormal Noises/Feelings	✔			
Parking Brake Operation	✔			
Front Exterior Lights	✔			
Wheels	✔			
Rear Exterior Lights	✔			
Paint Condition	✔			Some minor PDR dents on hood and trunk lid.

FLUIDS	Passing	Future Attention	Immediate Attention	Notes
Engine Oil	✔			Oil Service Completed. Valve cover gasket replaced.
Coolant	✔			
Power Steering Fluid	✔			
Transmission Fluid	✔			
Brake Fluid Condition	✔			

MECHANICAL	Passing	Future Attention	Immediate Attention	Notes
Front Suspensiton/Steering	✔			
Front Brakes	✔			10mm
Drive Belt Condition	✔			
Front Axles	✔			
Spare Tire and Equipment	✔			
Rear Suspension	✔			
Rear Brakes	✔			10mm
Rear Axles	✔			
Engine Oil Leaks	✔			
Cooling System Leaks	✔			
Power Steering Fluid Leaks	✔			
Driveshaft Condition	✔			
Drivetrain Fluids	✔			Fluids clean and at correct level
Drivetrain Mounts	✔			
Exhaust Condition	✔			
Engine Air Filter Service Interval	✔			
Cabin Air Filter Service Interval	✔			
Spark Plug Service Interval	✔			

OTHER TECH NOTES

Naturally aspirated N52 inline-six runs smoothly with no abnormal valvetrain noise or drivability concerns noted.