Vehicle Inspection Report

Inspection Completed By: Bryan Boyd, Master Technician, Ken Caryl Imports

Year/Make/Model: 2025 Porsche Cayenne Coupe
VIN: WP1BA2AY1SDA32598
Stock #: 2349

TIRES	>6/32	4-6/32	<4/32	Notes
LF	✓			6/32
RF	✓			6/32
LR	✓			6/32
RR	✓			6/32

TEST DRIVE	Passing	Future Attention	Immediate Attention	Notes
Maintenance Reminders	✓			
Malfunction Lights On	✓			
Acceleration/Performance	✓			
Transmission/Clutch Performance	✓			
Braking Performance/Noise	✓			
Steering Wheel Centered/Pulling	✓			
Horn Operation	✓			
Windshield Condition	✓			
Windshield Wiper/Jet Operation	✓			
Door Window Operation	✓			
Sunroof	✓			
Media and Infotainment	✓			
Mirrors and Seats	✓			
Climate Control Operation	✓			
Dome Light Operation	✓			
Additional Interior Notes	✓			
Abnormal Noises/Feelings	✓			
Parking Brake Operation	✓			
Front Exterior Lights	✓			
Wheels	✓			
Rear Exterior Lights	✓			
Paint Condition	✓			

FLUIDS	Passing	Future Attention	Immediate Attention	Notes
Engine Oil	✓			Oil Service Completed.
Coolant	✓			
Power Steering Fluid	✓			
Transmission Fluid	✓			
Brake Fluid Condition	✓			

MECHANICAL	Passing	Future Attention	Immediate Attention	Notes
Front Suspensiton/Steering	✓			
Front Brakes	✓			8mm
Drive Belt Condition	✓			
Front Axles	✓			
Spare Tire and Equipment	✓			
Rear Suspension	✓			
Rear Brakes	✓			8mm
Rear Axles	✓			
Engine Oil Leaks	✓			
Cooling System Leaks	✓			
Power Steering Fluid Leaks	✓			
Driveshaft Condition	✓			
Drivetrain Fluids	✓			Fluids clean and at correct level
Drivetrain Mounts	✓			
Exhaust Condition	✓			
Engine Air Filter Service Interval	✓			
Cabin Air Filter Service Interval	✓			
Spark Plug Service Interval	✓			

OTHER TECH NOTES

3.0L turbocharged V6 runs smoothly with no abnormal engine noise, warning messages, or drivability concerns noted.
8-speed Tiptronic transmission and all-wheel-drive system operate smoothly with no irregular engagement or shifting behavior observed.
Suspension, steering, brakes, and underbody components were inspected and appear to be in very good condition consistent with the vehicle’s age.
Major electrical, infotainment, driver-assistance, and convenience features were checked and found to be operating normally at the time of inspection.